Table 1-2 AOC Elements and Newark Bay Study Area RIWP Cross-Reference Table

AOC Element		RIWP Corresponding Location	Page Number
Invento	ory and Overview Report	Volume 1	
	•		
Investi	gation Work Plan (IWP)		
1.	Distribution of Constituents In Sediments		
	a. Coring locations and sampling depths	Section 6 of Volume 2	6-8
	b. Chemistry and Radiodating	Section 6 of Volume 2	6-6
2.	Human and Ecological Risk Assessment	Section 4 of Volume 2	4-15
3.	Direct and Indirect Source Identification		
	a. Fate/Transport Model	Section 4 of Volume 2	4-11
	b. Storm Water/CSO Characterization	Section 4 of Volume 2	4-17
Sampli	ng and Analysis Plan (SAP)		
1.	Sampling Location Maps	Section 6 of Volume 2	6-8
2.	Sampling Methods	Section 6 of Volume 2	6-22
3.	Sampling Frequency	Section 6 of Volume 2	6-5
4.	Analytical Methods	Section 6 of Volume 2	6-30
5.	Data Usefulness	Section 8 of Volume 2	8-6
6.	Milestones	Section 10 of Volume 2	10-1
Site Ma	nagement Plan (SMP)		
1.	Contractor/Subcontractor Identification	Section 5 of Volume 2	5-2
2.	Listing of Key Employees/Responsibilities	Section 5 of Volume 2	5-2
Quality Assurance Project Plan (QAPP)			
1.	Project Description	Sections 4 and 6 of Volume 2	4-1, 6-1
2.	Project Organization and Responsibility	Section 5 of Volume 2	5-1
3.	Quality Assurance Objectives	Section 5 of Volume 2	5-4
4.	Sampling Procedures	Section 6 of Volume 2	6-22
5.	Sample Custody	Section 6 of Volume 2	6-26
6.	Calibration Procedures and Frequency	Section 6 of Volume 2	6-45
7.	Analytical Procedures	Section 6 of Volume 2	6-30
8.	Data Reduction, Validation, and Reporting	Section 8 of Volume 2	8-1
9.	Internal Quality Control Checks	Section 6 of Volume 2	6-40
	Performance and Systems Audits	Section 7 of Volume 2	7-1
	Preventive Maintenance	Section 6 of Volume 2	6-45
12.	Procedures Used to Assess Data	Section 5 of Volume 2	5-6
	Precision, Accuracy and Completeness		
13.		Section 7 of Volume 2	7-5
14.	Quality Assurance Reports to Management	Section 6 of Volume 2	6-48
			1

Newark Bay Study Area RIWP
Sediment Sampling and Source Identification Program
Volume 2a of 3
IWP
Revision 1
September 2005

Table 1-2 (cont'd) AOC Elements and Newark Bay Study Area RIWP Cross-Reference Table

	AOC Element	RIWP Corresponding Location	Page Number
Health	and Safety/Contingency Plan (HASCP)		
1.	Known hazards and evaluation of the risks	Section 3 of Volume 3	3-1
2.	Key personnel responsible for safety	Section 2 of Volume 3	2-1
3.	Operations and governmental notification/coordination	Section 9 of Volume 3	9-1
4.	Levels of protection	Section 5 of Volume 3	5-1
5.	Decontamination procedures for personnel and equipment	Section 7 of Volume 3	7-3
6.	Incident emergency procedures	Section 9 of Volume 3	9-1
7.	Medical Surveillance Programs	Section 8 of Volume 3	8-3
8.	Monitoring for personnel safety	Section 6 of Volume 3	6-1
9.	Routine and special personnel training programs	Section 8 of Volume 3	8-1